Name(s) of Risk Team Members:  J. Durnan, J. D'Ambra, E. Sperry			Point Valu	1				2	3		4				5		
Job Title: Magnet Research & Development Technicians  Job Number or Job Identifier: 29-06			Frequen (B)	≤once/year			ar	≤once/month	≤once/week	≤once/shift			>once/shift				
Job Description: Transferring LN2 for MAGCOOL to Lab 32 and transferring to Cryostat and system			Severit (C)	First Aid Only				Medical Treatment	Lost Time	Partial Disability				Death or Permanent Disability			
Training and Procedure List (Optional):  Approved by: £. Lessard Date: 6-2-06 Rev. #: 0			Likeliho (D)	Likelihood (D)				nlikely	Unlikely	Possible	Probable			Multiple		ltiple	
Stressors (if applicab	Stressors (if applicable, please list all):  Reason				r Revision (if applicable): Comments:												
			Bef	Before Additional Controls After									fter Additional Controls				
Job Step / Task	Hazard	Control(s)	Stressors Y/N	# of People A	Frequency B	Severity C	Likelihood D	Risk*  AxBxCxD  Control(s) Ac	Stressors Y/N	# of People A	Frequency B	Severity C	Likelihood D	Risk* AxBxCxD	% Risk Reduction		
Moving storage vessel (dewar) to/from location	Overexertion injuries caused by excessive lifting, pushing, pulling, holding or carrying an object	Wheeled dewars, training, safety sl	hoes	N	1	4	3	3	36								
Moving storage vessel (dewar) in elevator	Oxygen deficiency	Training, no persons in elevator	N	1	4	1	1	4									
Connecting or disconnecting storage dewar to	Falls to lower level from step stool or other cryostat access	Step stool design, equipment inspetraining	ection, Tier 1,	N	1	4	2	1	8								
cryostat	Being struck by object due to pressure release	Vessel design/certification, equipment inspection, training, Safety glasses	N	1	4	2	2	16									
	Contact with temperature extremes that result in such injuries frost bite or burns	Training, procedures, gloves, eye proper clothing	N	1	4	2	2	16									
	Oxygen deficiency	Training, posting, safety reviews, v ODH calculations, doors stay open	ı, alarms	N	1	4	1	2	8								
Transferring cryogenic liquid	Being struck by object due to pressure release	Vessel design/certification, equipment inspection, training, Tier 1	nent	N	1	4	2	2	16								

from storage dewar to cryostat	Contact with temperature extremes that result in such injuries frost bite or burns	Training, procedures, gloves, eye protect proper clothing		N	1	4	2	2	16										
	Oxygen deficiency	Training, posting, safety reviews, ventile ODH calculations, doors stay open	ation,	N	1	4	1	2	8										
Transferring cryogenic fluid to portable dewar	Contact with temperature extremes that result in such injuries frost bite or burns	Training, procedures, gloves, eye protect proper clothing	etion,	N	1	4	2	2	16										
	Oxygen deficiency	Training, posting, safety reviews, ventilation, ODH calculations, doors stay open		N	1	4	1	2	8										
	Cut by sharp object due to breakage of glass thermos dewar	Training, procedures, gloves, eye protect proper clothing, wrapping dewar with ta	,	N	1	2	2	2	8										
Further Description of Controls Added to Reduce Risk:																			
*Risk:	0 to 20	21 to 40	21 to 40			41-60	)				61 to 80				81 or greater				
	Negligible	Acceptable				Mode	derate				Substantial	Substantial			Intolerable				